

Operator: BONANZA CREEK ENERGY OPERATING COMPANY LLC

Location Name: State North Platte FED F-36 Pad

Loc ID: 433511

Inspection: 708200983



Exhibit A



Exhibit B



Exhibit C



Exhibit D



Exhibit E



Exhibit F



Exhibit G



Exhibit H



Exhibit I



Exhibit J

CA: Open excavations were not adequately fenced at the time of this inspection. Refer to attached inspection photos for documentation. Fence or cover open excavations to prevent access when sites are not attended per Rule 913.b.(5)B.i.

CA Resolution: Operator has reported that all open excavations/holes have been backfilled as of 3/14/2024.

CA: This location does not comply with Reclamation rules. Rule 1002.c. states all stockpiled soils shall be protected from degradation due to contamination, compaction and, to the extent practicable, from wind and water erosion during drilling and production operations. During this inspection, it was observed that the topsoil stockpile and cut/fill slopes around the construction area were not properly stabilized with evidence of wind erosion and blow sand deposition. Additional BMPs are required. Refer to attached inspection photos.

CA Resolution: Operator reported that the location has been hydromulched to address/prevent erosion and provide stabilization. The location has also been re-seeded and straw crimped to establish desirable vegetation to comply with reclamation rules.