

**Inspection Photos**  
**Location Name: Hahn 1-4H**  
**Location ID: 424891**



**Photo 1 – Pumping Unit**

**Photo 2 – Stained Soil at Exhaust**

Inspection Photos  
Location Name: Hahn 1-4H  
Location ID: 424891



**Photo 3 – Propane Tanks**




**Photo 4 – Gas Engine – Stained Soil**

Inspection Photos  
Location Name: Hahn 1-4H  
Location ID: 424891



Energy and Carbon Management Commission  
40.59716, -104.31896, 4816.6ft  
03/21/2024 14:51:28

**Photo 5 – Stained Soil**



Energy and Carbon Management Commission  
40.59716, -104.31916, 4817.0ft  
03/21/2024 14:51:57

**Photo 6 – Wellhead – Stained Soil**

**Inspection Photos**  
**Location Name: Hahn 1-4H**  
**Location ID: 424891**



Energy and Carbon Management Commission  
40.59688, -104.3193, 4827.5ft  
03/21/2024 14:52:16



Energy and Carbon Management Commission  
40.59685, -104.31957, 4829.4ft  
03/21/2024 14:52:32

**Photo 7 – Tank Battery**

**Photo 8 – Tank Battery Sign**

**Inspection Photos**  
**Location Name: Hahn 1-4H**  
**Location ID: 424891**



**Photo 9 – Heater Treater and Gas Meter**



**Photo 10 – ECD and Flare**