

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

403711481

Date Received:

03/26/2024

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

### COGCC INSPECTION SUMMARY:

FIR Document Number: 708901945

Inspection Date: 10/12/2023

FIR Submit Date: 10/13/2023

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

#### LOCATION - Location ID: 335043

Location Name: SAVAGE-67S94W Number: 9SWNW County: \_\_\_\_\_

Qtrqtr: SWN Sec: 9 Twp: 7S Range: 94W Meridian: 6

Latitude: 39.455614 Longitude: -107.899064

#### FACILITY - API Number: 05-045-00 Facility ID: 335043

Facility Name: SAVAGE-67S94W Number: 9SWNW

Qtrqtr: SWN Sec: 9 Twp: 7S Range: 94W Meridian: 6

Latitude: 39.455614 Longitude: -107.899064

### CORRECTIVE ACTIONS:

1 CA# 185037

Corrective Action: Vents on pressure safety devices will terminate in a manner so as not to endanger the public or adjoining facilities. They will be designed to be clear and free of debris and water at all times.

Date: 10/20/2023

Response: CA COMPLETED

Date of Completion: 10/26/2023

Operator Comment: Rupture disc was capped. Corrective Action complete.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 185038

Corrective Action: All load lines will be capped or plugged

Date: 10/20/2023

Response: CA COMPLETED

Date of Completion: 10/26/2023

Operator  
Comment:

Load line was plugged. Corrective Action complete.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA# 185037: Rupture disc was capped. Corrective Action complete.  
CA# 185038: Load line was plugged. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed: \_\_\_\_\_

Title: TEP Representative

Date: 3/26/2024 5:27:08 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files