

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/27/2024

Submitted Date:

03/27/2024

Document Number:

702403252**FIELD INSPECTION FORM**Loc ID 336277 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email            | Comment                         |
|--------------|-------|------------------|---------------------------------|
| ,            |       | cogcc@kpk.com    | <a href="#">All Inspections</a> |
| ,            |       | rwatzman@kpk.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 241023      | WELL | SI     | 05/01/2021  | OW         | 123-08811 | NESSU 2       | SI          |

**General Comment:**[This is a wellsite inspection.](#)

**Location**Overall Good: ☒**Signs/Marker:**

|                    |   |       |  |
|--------------------|---|-------|--|
| Type               | WELLHEAD  |       |  |
| Comment:           | adequate the sign is peeling and will need to be replace in the near future |       |  |
| Corrective Action: |   | Date: |  |

Emergency Contact Number:

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  | Date: |  |
| Corrective Action: |  | Date: |  |

Overall Good: ☒**Spills:**

|      |      |        |  |  |
|------|------|--------|--|--|
| Type | Area | Volume |  |  |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

|                    |   |       |  |
|--------------------|---|-------|--|
| Type               | PUMP JACK   |       |  |
| Comment:           | fabricated square tubing/hog panel                          |       |  |
| Corrective Action: |   | Date: |  |
| Type               | OTHER   |       |  |
| Comment:           | Ancillary equip. has fabricated steel pipe and round stock. |       |  |
| Corrective Action: |   | Date: |  |

**Equipment:**

|                           |   |       |                 |
|---------------------------|---|-------|-----------------|
| Type: Pump Jack           | # 1                                     |       | corrective date |
| Comment:                  |   |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Bradenhead          | # 1                                     |       |                 |
| Comment:                  |   |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Ancillary equipment | # 1                                     |       |                 |
| Comment:                  | electric panel, meter box & transformer |       |                 |
| Corrective Action:        |   | Date: |                 |
| Type: Prime Mover         | # 1                                     |       |                 |
| Comment:                  | electric motor                          |       |                 |
| Corrective Action:        |   | Date: |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

|                    |  |       |  |
|--------------------|--|-------|--|
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

| Inspected Facilities    |        |   |      |  |           |             |       |               |    |            |
|-------------------------|--------|---|------|--|-----------|-------------|-------|---------------|----|------------|
| Facility ID:            | 241023 | Type:   | WELL | API Number:                                    | 123-08811 | Status:     | SI    | Insp. Status: | SI |            |
| Idle Well               |        |   |      |  |           |             |       |               |    |            |
| Purpose:                |        | <input checked="" type="checkbox"/> Shut In   |      | <input type="checkbox"/> Temporarily Abandoned |           | Reminder:   |       |               |    |            |
| Comment:                |        | <div>SI since 5-2021 &amp; last produced 4/2021. Well is overdue for Mechanical Integrity Test. MIT requires 10-day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.</div> |      |  |           |             |       |               |    |            |
| Corrective Action:      |        | <div>Produce well after performing successful mechanical integrity test per Rule 417 or plug well. To maintain shut-in status, the well must be able to demonstrate ability to produce without mechanical intervention.</div> |      |  |           |             | Date: |               |    | 04/27/2024 |
| BradenHead              |        |   |      |  |           |             |       |               |    |            |
| Date of Last Brhd Test: |        | 10/04/2023  |      | Annual Brhd Completed?                         |           | Yes         |       |               |    |            |
| Last Brhd Test Results  |        | Initial Surf Csg Pressure:  |      | 0  |           | Fluid Type: |       |               |    |            |
|                         |        | End Surf Csg Pressure:  |      | 0  |           |             |       |               |    |            |
| Comment:                |        | <div>plumbed to surface</div>   |      |  |           |             |       |               |    |            |
| Corrective Action:      |        |   |      |  |           |             | Date: |               |    |            |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <p>ECMC Inspection Report Summary<br/>On Wednesday 3-27-2024 at approximately 1515 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection: This Field Inspection is due to a 901 order.<br/>Operator: KP Kauffman<br/>Location name:<br/>Location ID # 336277<br/>Well Name: Nessu 2<br/>API # 05-123-08811<br/>County: Weld<br/>Weather: Clear<br/>Location: Dry<br/>While there, I observed a wellsite, SI at the time of the inspection.<br/>During this inspection, I observed the following possible compliance issues:<br/>417.b MIT: SI wells, CA date 4-27-2024.<br/>See attached photos.<br/>A follow up site inspection is needed to ensure that the addressed Compliance issues comply with ECMC rules.<br/>Any Corrective Actions from previous inspections not addressed are still applicable.</p> | revasr | 03/27/2024 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description     | URL   |
|--------------|-----------------|---|
| 702403253    | location photos | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6484093">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6484093</a> |