

Inspection Photos

API: 017-06625

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 3/26/2024

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing east along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road must be maintained and shall not drive outside of the access road boundary.



Inspection Photos



Photo 2. Facing east along the access road. Vehicles are causing unnecessary disturbance driving outside of the access road due to stormwater pooling on the road. The access road must be maintained and shall not drive outside of the access road boundary.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos



Photo 3. Facing northeast toward the wellsite. There is oil leaking out of the wellhead that must be controlled and cleaned up.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:017-06625 | Date: 3/26/2024

Inspection Photos



Photo 4. View of oil that has leaked out of the well.



Inspection Photos



Photo 5. There is oil coming out of the exhaust pipe which is staining the soil and needs to be cleaned up.



Inspection Photos



Photo 6. There is lube oil leaking out of the pumpjack engine that must be controlled and cleaned up.



Inspection Photos



Photo 7. View of inside the shed where oil is leaking out of the pumpjack engine.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:017-06625 | Date: 3/26/2024

Inspection Photos



Photo 8. The red arrows point to oily impacted soils coming from the pumpjack.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API:017-06625 | Date: 3/26/2024