

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/21/2024

Submitted Date:

03/21/2024

Document Number:

707901449

**FIELD INSPECTION FORM**Loc ID 331435 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.
,	303-825-4822	cogcc@kpk.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
262053	WELL	PR	02/01/2023	GW	123-20683	COAN 17-33 17-33	SI

**General Comment:**

This is a follow up inspection per Doc#707901335

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
<b>Good Housekeeping:</b>				
Type	OTHER			
Comment:	Reporting No Firr was submitted to ECMC			
Corrective Action:	Comply with rule 210			Date:
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:				Date:
<b>Flaring:</b>				
Type				
Comment:				
Corrective Action:				Date:

**Inspected Facilities**Facility ID: 262053 Type: WELL API Number: 123-20683 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: SI At time of inspectio flow line appear to be in the closed position.Corrective Action:  Date: **COGCC Comments**

Comment	User	Date
This is a follow up inspection per doc# 707901335. At time of inspection it appears the only corrective address and completed was mechanical issue for the Hozontal seperator burner stack installed. At time of inspection all other corrective action had not been addressed. Road and facility had been mowed but as stated in previous inspection road and location had debris that needed to be removed from seconday containment and around equipment, and road need to be maintained per photos neither were completed fully. In addition Production reports and braden head reports that wre requested by inspector by 2-20-24 they were not recevied through the FIRR process. KPK will recieve a corrective action for non reporting of FIRR and do non compliance of corrective actions in previous inspection, inspection will be submitted for NOAV.	silverr	03/21/2024

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403728247	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6477552">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6477552</a>
707901450	loc pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6477550">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6477550</a>