

Storm Water Management and Erosion control
Location Name: TEP Rocky Mountain LLC SAVAGE RMV 48-35 Pad
Location # 334873



**Location Overview: Location is within High
Priority/Density/Black Bear Habitat areas.**
Section/Township/Range: 35 6S94W

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC SAVAGE RMV 48-35 Pad
Location # 334873



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC SAVAGE RMV 48-35 Pad
Location # 334873



Photo # 1271 Ditch/BMP near entrance to location needs maintenance/sediment buildup & small breach in ditch allowing sediment transport from ditch into the interim area & causing more erosion & sediment transport in the interim area itself.

Photo # 1272 Ditch/BMP near entrance to location needs maintenance/sediment buildup & small breach in ditch allowing sediment transport from ditch into the interim area & causing more erosion & sediment transport in the interim area itself.

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC SAVAGE RMV 48-35 Pad
Location # 334873



Photo # 1273 Ditch/BMP near entrance to location needs maintenance/small breach in ditch allowing sediment transport from ditch into the interim area & causing more erosion & sediment transport in the interim area itself.



Photo # 1274 Ditch/BMP near entrance to location needs maintenance/small breach in ditch allowing sediment transport from ditch into the interim area & causing more erosion & sediment transport in the interim area itself.

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC SAVAGE RMV 48-35 Pad
Location # 334873



Photo # 1275 Ditch/BMP near entrance to location needs maintenance/small breach in ditch allowing sediment transport from ditch into the interim area & causing more erosion & sediment transport in the interim area itself.



Photo # 1276 Check dam/BMP needs maintenance.

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC SAVAGE RMV 48-35 Pad
Location # 334873



Photo # 1277 Check dam/BMP needs maintenance.



Photo # 1278 Check dam/BMP needs maintenance.

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC SAVAGE RMV 48-35 Pad
Location # 334873



Photo # 1279 Check dam/BMP needs maintenance.



Photo # 1280 Check dam/BMP needs maintenance.

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC SAVAGE RMV 48-35 Pad
Location # 334873



Photo # 1281 Check dam/BMP needs maintenance.



Photo # 1282 Check dam/BMP needs maintenance.

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC SAVAGE RMV 48-35 Pad
Location # 334873



Photo # 1283 Rill erosion & transport of sediment off location/insufficient runoff controls/BMP's



Photo # 1284 Rill erosion & transport of sediment off location/insufficient runoff controls/BMP's

Storm water Management and Erosion control
Location Name: TEP Rocky Mountain LLC SAVAGE RMV 48-35 Pad
Location # 334873



Photo # 1285 Rill erosion & transport of sediment off location/insufficient runoff controls/BMP's