

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/19/2024

Submitted Date:

03/25/2024

Document Number:

714000584

**FIELD INSPECTION FORM**Loc ID 326291 Inspector Name: Mcdonough, Corey On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

OGCC Operator Number: 10133

Name of Operator: HILCORP ENERGY COMPANY

Address: P O BOX 61229

City: HOUSTON State: TX Zip: 77208

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name      | Phone        | Email                                 | Comment            |
|-------------------|--------------|---------------------------------------|--------------------|
| Shorty, Priscilla | 505-324-5188 | pshorty@hilcorp.com                   | All Inspections SW |
| , General         |              | FarmingtonRegulatoryTechs@hilcorp.com | All SW Inspections |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name        | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------|-------------|
| 216181      | WELL | PR     | 10/10/1991  | CBM        | 067-07787 | SE DURANGO-WRIDE 6-1 | RI          |

**General Comment:**

On 3/19/2024 Reclamation Specialist Corey McDonough conducted a Storm Water and Reclamation Inspection at Hilcorp Energy Companies SE Durango Wride 6-1 Location in La Plata County, Colorado. This is a follow up inspection to inspection doc # 714000052.

During the inspection the following compliance issues were observed

- Unused equipment

Refer to the "Good House-keeping" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

|  |   |        |  |                  |
|--|---|--------|--|------------------|
| Location   |   |        |  |                  |
| Overall Good: <input type="checkbox"/>                 |   |        |  |                  |
| Emergency Contact Number:                              |   |        |  |                  |
| Comment:   |   |        |  | Date: _____      |
| Corrective Action:                                     |   |        |  |                  |
| Good Housekeeping:                                     |   |        |  |                  |
| Type   | UNUSED EQUIPMENT  |        |  |                  |
| Comment:   | Unused panel observed on location.                                |        |  |                  |
| Corrective Action:                                     | Comply with rule 606. Remove and properly store unused equipment. |        |  | Date: 04/09/2024 |
| Overall Good: <input type="checkbox"/>                 |   |        |  |                  |
| Spills:  |   |        |  |                  |
| Type   | Area  | Volume |  |                  |
| In Containment: No                                     |   |        |  |                  |
| Comment:   |   |        |  |                  |
| <input type="checkbox"/> Multiple Spills and Releases? |   |        |  |                  |
| Venting:   |   |        |  |                  |
| Yes/No   |   |        |  |                  |
| Comment:   |   |        |  |                  |
| Corrective Action:                                     |   |        |  | Date:            |
| Flaring:   |   |        |  |                  |
| Type   |   |        |  |                  |
| Comment:   |   |        |  |                  |
| Corrective Action:                                     |   |        |  | Date:            |

| Inspected Facilities |        |       |      |             |           |         |    |               |    |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 216181 | Type: | WELL | API Number: | 067-07787 | Status: | PR | Insp. Status: | RI |

|  |
|--|
|  |
|--|

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: [Revegetation is progressing within the interim reclamation areas.](#)**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? \_\_\_\_\_ Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation In Process

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|                  |                 |                         |                       |               |                          |         |

Comment:

At the time of the inspection, no storm water erosion issues were observed. Continue monitoring and managing storm water and erosion controls to ensure compliance with storm water regulations.

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 403730463    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6480612">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6480612</a> |
| 714000590    | Inspection Photos    | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6480596">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6480596</a> |