

Inspected Facilities

Facility ID: 415409 Type: WELL API Number: 123-31051 Status: TA Insp. Status: EI

Facility ID: 485784 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

Environmental

Spill/Remediation:

Comment: [ECMC Environmental Inspection Remediation Project 30818 for well plugging, cut & cap and Rule 911 assessment. Historical Release reported 12/26/2023. Well site is backfilled. ECMC received Supplemental Form 27 by February 6, 2024 with a proposed workplan for soil borings and possible monitoring wells. ECMC observed the presence of 2" piezometers installed on location. Per Form 27 Initial, flowline was previously abandoned prior to January 15, 2021.](#)

[ECMC expects Supplemental Form 27 on a quarterly basis with next Supplemental Form 27 due May 6, 2024.](#)

Corrective Action:

Date: _____

Emission Control Burner (ECB): _____

Comment:

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693701132	Shable USXAB11-16Pwellsite3-22-2024	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6488793