

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/01/2024

Submitted Date:

04/01/2024

Document Number:

713300779

**FIELD INSPECTION FORM**Loc ID 311301 Inspector Name: Kester, Michael On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1700 LINCOLN ST STE 4550

City: DENVER State: CO Zip: 80203

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, KPK	303-825-4822	cogcc@kpk.com	all inspections
Silver, Randy	720-827-6688	randy.silver@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241384	WELL	PR	10/01/2023	OW	123-09173	UPRR 43 PAN AM I 7	PR

**General Comment:**

Routine inspection with corrective action

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	good		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

<b>Good Housekeeping:</b>		
Type	UNUSED EQUIPMENT	
Comment:	tubing and rods	
Corrective Action:	Comply with Rule 606	Date: 05/01/2024

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>		
Type	PUMP JACK	
Comment:	safety guards	
Corrective Action:		Date:
Type	OTHER	
Comment:	electric/automation disconnects, metal panel	
Corrective Action:		Date:
Type	WELLHEAD	
Comment:	chain link panels	
Corrective Action:		Date:

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	pipd to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 3		
Comment:	automation/electric panels		
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
<b><u>Venting:</u></b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<b><u>Flaring:</u></b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 241384 Type: WELL API Number: 123-09173 Status: PR Insp. Status: PR**Producing Well**Comment: PR Valves appeared to be open at time of inspection

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 01/08/2024 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
ECMC Inspection Report Summary Inspector Michael Kester, conducted on-site inspection Location: UPRR 43 PanAm I 7 Operator: KPK API#: 123-09173 County: Weld While there, I observed well site with pumping unit, During this inspection, the following possible compliance issues were observed: Unused equipment, Rule 606, corrective action date 5-1-2024 Photo 3 & 4  Weather conditions: overcast and dry A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with ECMC rules. This is a summary of inspection report.  This inspection does not nullify any orders or NOAV from the ECMC This is a continuing education inspection	kesterm	04/01/2024

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713300780	site pic	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6490214">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6490214</a>