

Caerus Piceance LLC  
Piceance Creek Unit-62S97W 7SENE  
Location ID: 335884



When replaced additional information is required. Operator contact information illegible.



Debris



Caerus Piceance LLC  
Piceance Creek Unit-62S97W 7SENE  
Location ID: 335884



Debris



Debris



Caerus Piceance LLC  
Piceance Creek Unit-62S97W 7SENE  
Location ID: 335884



**Sign not visibly displayed**




**Unused equipment.**





Caerus Piceance LLC  
Piceance Creek Unit-62S97W 7SENE  
Location ID: 335884



Debris



Debris



Caerus Piceance LLC  
Piceance Creek Unit-62S97W 7SENE  
Location ID: 335884



**Lack of stabilization. Vehicle tracking.**



**Lack of stabilization. Vehicle tracking.**



**Caerus Piceance LLC**  
**Piceance Creek Unit-62S97W 7SENE**  
**Location ID: 335884**



**Debris**



**Relief riser missing rain protection**



Caerus Piceance LLC  
Piceance Creek Unit-62S97W 7SENE  
Location ID: 335884



**Relief risers missing rain protection**



**Debris**



Caerus Piceance LLC  
Piceance Creek Unit-62S97W 7SENE  
Location ID: 335884



Debris



Debris. Unused equipment.



Caerus Piceance LLC  
Piceance Creek Unit-62S97W 7SENE  
Location ID: 335884



**Debris**




**Debris. Bear proof container required if food waste is present.**



Caerus Piceance LLC  
Piceance Creek Unit-62S97W 7SENE  
Location ID: 335884



Faded and illegible labels



Debris. Unused equipment.



**Caerus Piceance LLC**  
**Piceance Creek Unit-62S97W 7SENE**  
**Location ID: 335884**



**Erosion and sediment migration**



**Vehicle tracking from production facility**



**Caerus Piceance LLC**  
**Piceance Creek Unit-62S97W 7SENE**  
**Location ID: 335884**



**Sediment migration. Vehicle tracking from well pad.**



**Erosion and sediment migration**



**Caerus Piceance LLC**  
**Piceance Creek Unit-62S97W 7SENE**  
**Location ID: 335884**



**Erosion and sediment migration**



**Erosion and sediment migration**



**Caerus Piceance LLC**  
**Piceance Creek Unit-62S97W 7SENE**  
**Location ID: 335884**



**Erosion and sediment migration**



**Access road to location. Vehicle tracking.**



**Caerus Piceance LLC**  
**Piceance Creek Unit-62S97W 7SENE**  
**Location ID: 335884**



**Well pad from Northeast corner**



**Well pad from Southeast corner**



**Caerus Piceance LLC**  
**Piceance Creek Unit-62S97W 7SENE**  
**Location ID: 335884**



**Well pad from Southwest corner**



**Well pad from Northwest corner**



Caerus Piceance LLC  
Piceance Creek Unit-62S97W 7SENE  
Location ID: 335884



Production facility from Southeast corner



Production facility from Northwest corner

