

Inspection Photos

Loc: 476137

Operator: **WILLIFORD ENERGY COMPANY**

Inspection Date: 3/26/2024

County: Cheyenne



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing southeast toward the tank battery,



Inspection Photos



Photo 2. There is oily sludge that has leaked out of the tank load out pipe. Secondary containment needs to be installed and the stained material must be cleaned up.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 476137 | Date: 3/26/2024

Inspection Photos



Photo 3. Tank battery sign is posted at west side gate.



Inspection Photos



Photo 4. Southeast side of the location facing northwest, The secondary containment has been eroded and needs to be rebuilt in this area.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 476137 | Date: 3/26/2024

Inspection Photos




Photo 5. Facing west at the battery. There is stained soils shown at red arrow that need to be cleaned up. The yellow arrow points to insulation debris that needs to be removed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 476137 | Date: 3/26/2024

Inspection Photos



Photo 6. Facing toward the northeast side of the tank battery. The berm along the area is worn down and needs to be built up better for containmat.

