

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/26/2024

Submitted Date:

04/03/2024

Document Number:

713600890

**FIELD INSPECTION FORM**

Loc ID: 476137 Inspector Name: COSTA, RYAN On-Site Inspection:  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96730  
Name of Operator: WILLIFORD ENERGY COMPANY  
Address: 6060 AMERICAN PLAZA SUITE 760  
City: TULSA State: OK Zip: 74135

**Findings:**

- 4 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
GROWNS LARRY		lgrowns@willifordenergy.com	
Storts, Doug		pds@willifordenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
476137	LOCATION	AC			-	RHOADES UNIT TUBING FLOWLINE 3213S48W	RI

**General Comment:**

This is a location inspection of the RHOADES UNIT Tank Battery.  
See attached photos and additional details within this report.

**Location**

Overall Good:

**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	<input style="width: 95%;" type="text"/>		
Corrective Action:	<input style="width: 95%;" type="text"/>	Date:	<input style="width: 80%;" type="text"/>

**Good Housekeeping:**

Type	DEBRIS		
Comment:	There was some insulation debris and used rags laying on the ground that need to be removed.		
Corrective Action:	Comply with Rule 606.		Date: 04/10/2024

Overall Good:

**Spills:**

Type	Area	Volume		
Crude Oil				
Comment:	There was oily sludge at the truck loadout which has no secondary containment. There was oil stained soils around the tanks and shed that will need to be cleaned up.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a. Immediately to stop and clean up 24 hours to remove free fluids. 30-days to remove stained soil.		Date:	05/03/2024

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

Paint

Condition	<input style="width: 95%;" type="text"/>
Other (Content)	<input style="width: 95%;" type="text"/>
Other (Capacity)	<input style="width: 95%;" type="text"/>
Other (Type)	<input style="width: 95%;" type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		Inadequate
Comment:	The berm at the southeast side of the location has eroded and must repaired. The berm at the northeast side is worn down and insufficient to contain a spill.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o. Comply with 902.b for Pollution prevention.			Date: 05/03/2024

<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600891	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6492588">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6492588</a>