

Final Reclamation and Stormwater Inspection

Date: 03/29/2024

Operator: KERR MCGEE OIL & GAS ONSHORE LP

Location ID: 333265

Inspection Document #: 708201087

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Trolco 65N67W
Location ID: 333265



Photo 1. Midstream equipment remains on the former tank battery location. Operator shall continue to work with Midstream Operator to remove equipment as soon as possible.

Inspection Photos
Location Name: Trolco 65N67W
Location ID: 333265



Photo 2. Taken from the southern portion of the former access road. Road base material has been removed and the former access road has been contoured/graded to match existing ag field.

Inspection Photos
Location Name: Trolco 65N67W
Location ID: 333265



Photo 3. Taken from the access road/southern portion of the location, facing south. See comments in Photo 2.

Inspection Photos
Location Name: Trolco 65N67W
Location ID: 333265



Photo 4. Taken from the access road/southern portion of the location, facing north. See comments in Photo 2

Inspection Photos
Location Name: Trolco 65N67W
Location ID: 333265



Photo 5. Taken from the eastern portion of the well location, facing northwest. The former well location has been contoured/graded to match existing ag field and all surface equipment has been removed. A follow-up inspection will be conducted at a later date to verify vegetative compliance with Rule 1004.

Inspection Photos
Location Name: Trollco 65N67W
Location ID: 333265



Photo 6. Taken from the southern portion of the well location, facing northeast. See comments in Photo 5.

Inspection Photos
Location Name: Trollco 65N67W
Location ID: 333265



Photo 7. Debris (wire) observed along the former access road.