


KT Resources LLC
 Ant Hill Unit 19-44
 Location ID: 316310



Entrance to location

Gas meter calibration overdue

**KT Resources LLC
Ant Hill Unit 19-44
Location ID: 316310**



Relief risers missing rain protection



Debris

**KT Resources LLC
Ant Hill Unit 19-44
Location ID: 316310**



Erosion and sediment migration



Debris

**KT Resources LLC
Ant Hill Unit 19-44
Location ID: 316310**



When replaced additional information is required



Soil staining

**KT Resources LLC
Ant Hill Unit 19-44
Location ID: 316310**



Debris

Debris

**KT Resources LLC
Ant Hill Unit 19-44
Location ID: 316310**



Illegible label



Debris

**KT Resources LLC
Ant Hill Unit 19-44
Location ID: 316310**



Debris



Sediment migration

**KT Resources LLC
Ant Hill Unit 19-44
Location ID: 316310**



Location from Northeast corner

Location from Southeast corner

**KT Resources LLC
Ant Hill Unit 19-44
Location ID: 316310**



Location from Southwest corner



Location from Northwest corner