

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/26/2024

Submitted Date:

03/28/2024

Document Number:

713600865

FIELD INSPECTION FORMLoc ID 321659 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 96730

Name of Operator: WILLIFORD ENERGY COMPANY

Address: 6060 AMERICAN PLAZA SUITE 760

City: TULSA State: OK Zip: 74135

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

5 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|-----------------------------|---------|
| Welsh, Brian | | brian.welsh@state.co.us | |
| GROWNS LARRY | | lgrowns@willifordenergy.com | |
| Storts, Doug | | pds@willifordenergy.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------|-------------|
| 207701 | WELL | PR | 11/11/2008 | OW | 017-06636 | RHOADES 44-31 5 | RI |

General Comment:

This is a location and stormwater management inspection of the RHOADES #44-31 5 wellsite.
See attached photos and additional details within this report.

Location**Lease Road:**

| | | | |
|--------------------|--|-------|------------|
| Type | Access | | |
| comment: | There are areas where vehicles are driving outside of the access road boundary causing unnecessary disturbance that will need to be reclaimed. Repeated or flagrant instance(s) of failure to restrict lease access to lease roads which result in unreasonable land damage or crop losses shall be subject to a penalty under Rule 523. | | |
| Corrective Action: | Operator shall abide by the reclamation rules to minimize surface disturbances per the 1002e rule. | Date: | 03/28/2024 |

Overall Good: ☐**Signs/Marker:**

| | | | |
|--------------------|---|-------|------------|
| Type | WELLHEAD | | |
| Comment: | The well sign is laying on the ground not properly installed. | | |
| Corrective Action: | Install sign to comply with Rule 605.d. | Date: | 04/30/2024 |

Emergency Contact Number:

| | | |
|--------------------|--|-------------|
| Comment: | | |
| Corrective Action: | | Date: _____ |

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | OTHER | | |
| Comment: | The electric utility is not maintained in a safe manner. The electric wire is laying on the ground and not connected to the breaker box. | | |
| Corrective Action: | Comply with 608.e. to maintain in good mechanical condition. | Date: | 04/05/2024 |

Overall Good: ☐**Spills:**

| | | | | | |
|--------------------|--|--------|--|-------|------------|
| Type | Area | Volume | | | |
| Lube Oil | Pump Jack | | | | |
| Comment: | There is oil leaking out of the pumpjack engine. It appears this leak has been ongoing for a duration of time and there is oil saturated soils. | | | | |
| Corrective Action: | Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906. Immediately to stop and clean up 24 hours to remove free fluids. 30-days to remove stained soil. | | | Date: | 03/28/2024 |

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|---------|
| | | Gravel | Fail | Material Handling And Spill Prevention | Fail | |

Comment: There are areas of access road which are not stabilized or maintained. It appears there are areas where stormwater is pooling and vehicles are driving around the impacted road causing unnecessary disturbance. The access road needs to be repaired and maintained with BMP's such as road base, gravel, culverts, ect. There is also an erosion channel coming from the wellsite along the road that will need to be repaired and stabilized. Corrective action will remian out of compliance until completed.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)

Date: 04/01/2024

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 403734891 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6485285 |
| 713600866 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6485282 |