

Inspection Photos

Loc: 483886

Operator: BNL (ENTERPRISE) INC

Inspection Date: 4/2/2024

County: LAS ANIMAS



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing north along the access road. The road needs to be built and stabilized with BMP's.



Inspection Photos



Photo 2. Facing north along the road. There is vehicle rutting that needs to be repaired and stabilized to prevent rutting and road damage. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:483886 | Date: 4/2/2024

Inspection Photos



Photo 3. Facing northwest toward the access road. The side of the road needs to be seeded and stabilized and the road needs to be crowned and graveled if the well is developed. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:483886 | Date: 4/2/2024

Inspection Photos



Photo 4. The vehicle ruts that went outside of the road will need to be raked and seeded. Previous corrective action was not completed.



Inspection Photos



Photo 5. Facing northwest toward the location.



Inspection Photos



Photo 6. Facing toward the drilled well. The drill cuttings have been removed.



Inspection Photos



Photo 7. Facing toward the soil stock pile. The stock pile will need to be seeded before the growing season unless it will be re-spread for reclamation before that time.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc:483886 | Date: 4/2/2024

Inspection Photos



Photo 8. There are several areas where the silt fence is not maintained.



Inspection Photos



Photo 9. Facing northwest at the corner of the location. Unused areas of the location will need to be recontoured and reclaimed with 6 months of drilling.

