

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/41-4

Location ID: 333109

Date: 4/4/2024



Location Entrance – Photo #00408




Wellheads – Photo #00406

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, GM/41-4

Location ID: 333109

Date: 4/4/2024



Wellhead – Photo #00409



Wellhead – Photo #00410

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/41-4

Location ID: 333109

Date: 4/4/2024



Separators – Photo #00411



Separators – Photo #00412

Inspection Photos


Location Name: TEP ROCKY MOUNTAIN LLC, GM/41-4

Location ID: 333109

Date: 4/4/2024



Tank Battery – Photo #00414



ECD – Photo #00413



Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GM/41-4

Location ID: 333109

Date: 4/4/2024



Lack of Stabilization – Photo #00415



Lack of Stabilization/Insufficient Vehicle Tracking BMPs at
Location Entrance/Exit – Photo #00416