

Inspected Facilities

Facility ID: 297684 Type: WELL API Number: 123-28035 Status: TA Insp. Status: EI

Environmental

Spill/Remediation:

Comment: ECMC Environmental Inspection Remediation Project 30774 for well plugging, cut & cap and Rule 911 assessment. Well site is backfilled. ECMC notes cut and cap date of 10/30/2023 on approved Form 6-S Document #403600555. ECMC expects a Supplemental Form 27 with well assessment data by January 28, 2024. No Supplemental Form 27 has been received.

ECMC notes flowline was abandoned prior to January 15, 2024 according to Initial Form 27 Document #403465233.

Corrective Action: Submit a Supplemental Form 27 with well assessment results.

Date: 04/29/2024

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403737570	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6488807
693701134	Shable14-24wellsite3-22-2024	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6488794