

# Interim Reclamation and Stormwater Inspection

Date: 4/4/24

Operator: Highpoint Operating Corporation - 10071

Location ID: 444717

Inspection Document #: 713900517

Weld County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

# Inspection Photos

Location Name: Anschutz Equus Farms

4-62-20\_21 SWNW

Location ID: 444717



ECMC  
21° N  
4/4/24, 12:30 PM

**Photo 1.** The photo was taken at the entrance to the tank battery location facing North. The photo illustrates the cattle guard at the entrance.



## Inspection Photos

Location Name: Anschutz Equus Farms

4-62-20\_21 SWNW

Location ID: 444717



**Photo 2.** The photo was taken at the tank battery location facing East. The photo illustrates the production pad boundary and perimeter berm.

**Photo 3.** The photo was taken from the tank battery location facing North. The photo illustrates unmarked well risers on the Southeast corner of the production pad.

Note - Interim areas shown on the right are dominated by Russian thistle.



# Inspection Photos

Location Name: Anschutz Equus Farms

4-62-20\_21 SWNW

Location ID: 444717



**Photo 4.** The photo was taken at the tank battery location facing North. The photo illustrates topsoil stockpile and interim areas dominated by Russian thistle.



**Photo 5.** The photo was taken at the tank battery location facing North. The photo illustrates unmarked risers on the East side of the production pad.



# Inspection Photos

Location Name: Anschutz Equus Farms

4-62-20\_21 SWNW

Location ID: 444717



**Photo 6.** The photo was taken at the tank battery location facing Southwest. The photo illustrates unmarked risers along the North of the production pad.

**Photo 7.** The photo was taken at the tank battery location facing West. The photo illustrates secondary containment without any wildlife protection such as netting.



# Inspection Photos

Location Name: Anschutz Equus Farms

4-62-20\_21 SWNW

Location ID: 444717



**Photo 8.** The photo was taken at the tank battery location facing Northwest. The photo illustrates a hose attached to production equipment without any type of plug.



**Photo 9.** The photo was taken at the tank battery location facing North. The photo illustrates stained soil that has been covered with gravel near the hose in the previous photo.