

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/29/2024

Submitted Date:

04/03/2024

Document Number:

697602317

FIELD INSPECTION FORMLoc ID 306510 Inspector Name: Ahmadian, Alexander On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289301	WELL	PA	11/16/2023	OW	123-24809	CAMP 2-31	EI
485768	SPILL OR RELEASE	CL	12/19/2023		-	Camp 2-31 O SA Facility	EI

General Comment:

This is an environmental inspection to determine progress on Facility ID 485768/Remediation 30492. Any corrective actions from previous inspections that have not been addressed are still applicable. Operator personnel was on location backfilling the site at the time of this field inspection. Photos attached to document site conditions.

Location

Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date:

Overall Good: ☒

Spills:

Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Date Run: 4/10/2024 Doc [#697602317]

Page 2 of 4

Inspected Facilities									
Facility ID:	289301	Type:	WELL	API Number:	123-24809	Status:	PA	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	485768	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental		
Spill/Remediation:		
Comment:	Operator did not provide any notification of backfill or any sampling events performed on location. The last approved Form 27 for this spill was received on July 17, 2023 (Doc # 403464907) and the last Form 19 was received December 20, 2023 (Doc # 403629533). No analytical data has been provided by Operator for this location. Operator has not submitted a form within the approved quarterly reporting schedule and Rule 913.e.(3); the next quarterly report was due March, 19, 2024..	
Corrective Action:	Operator shall immediately submit a Form 27 for Spill ID 478542 with analytical data justifying backfill of this location and that includes a specific workplan and timeline.	Date: 03/19/2024
Emission Control Burner (ECB): _____		
Comment: _____		
Pilot: _____ Wildlife Protection Devices (fired vessels): _____		

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403741527	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6493416
697602318	Site photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6493409