

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/29/2024

Submitted Date:

04/03/2024

Document Number:

697602321

FIELD INSPECTION FORM

Loc ID 332527 Inspector Name: Ahmadian, Alexander On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

ECMC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1099 18TH STREET SUITE 1500
City: DENVER State: CO Zip: 80202

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@chevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289432	WELL	TA	10/03/2023	GW	123-24840	ROBERT 28-14	EI
485802	SPILL OR RELEASE	AC	01/05/2024		-	Robert 28-14	EI

General Comment:

This is an environmental inspection to determine progress on Facility ID 485802. Any corrective actions from previous inspections that have not been addressed are still applicable. No Operator or contract environmental personnel was on location at the time of this field inspection. Photos attached to document site conditions.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:					
Type	WELLHEAD				
Comment:	Fencing around the wellhead does not fully surround the wellhead and the fencing was broken.				
Corrective Action:	Oil and Gas Facilities will be adequately fenced to restrict access by unauthorized persons.			Date:	04/10/2024

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 289432 Type: WELL API Number: 123-24840 Status: TA Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 485802 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Environmental

Spill/Remediation:

Comment:	The last approved Supplemental Form 19 for this spill was received on Decemeber 28, 2023 (Doc # 403639335). No analytical data has been provided by Operator for this location.	
Corrective Action:	Operator shall immediately submit a Form 19 since the 90 days has passed. If impacts remain in-situ Operator will immediately submit a Form 19 and Form 27 that includes a specific workplan and timeline to address the remaining impacts.	Date: <u>03/27/2024</u>

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403742085	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6494099
697602322	Photolog	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6494097