

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/02/2024

Submitted Date:

04/02/2024

Document Number:

708301957

## FIELD INSPECTION FORM

 Loc ID 334269 Inspector Name: Morris, Matthew On-Site Inspection  2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 15 Number of Comments  
 8 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**

**Operator Information:**
 ECMC Operator Number: 10770  
 Name of Operator: VISION ENERGY LLC  
 Address: P O BOX 370  
 City: IGNACIO State: CO Zip: 81137
**Contact Information:**

Contact Name	Phone	Email	Comment
ENERGY, VISION		mco@visionenergy.biz	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210984	WELL	SI	05/01/1996	CBM	045-06742	SOUTH SHALE RIDGE 1-8	SI
266868	WELL	SI	11/01/2007	CBM	045-09186	SOUTH SHALE RIDGE 1-8H	SI

**General Comment:**[COGCC Inspection Report Summary](#)

On 4/2/2024 at approximately 10:10, Compliance Inspector Matthew Morris conducted a follow-up inspection at VISION ENERGY LLC, SOUTH SHALE RIDGE-68S98W/8NENE at Location ID #334269 in Garfield County, Colorado.

Normal production operations were observed.

During the inspection, the following compliance issues were observed:

- 1) No tank battery sign posted
- 2) Wellhead signs and tank labels contain inaccurate operator information
- 3) Unused equipment stored on location
- 4) Weeds have compromised permeability of tank battery berms
- 5) Stormwater; refer to Stormwater section

A follow-up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.

This location is within or in close proximity to, a CPW Density/High Priority Habitat, Black Bear, NSO Habitat, or Wildlife Management area.

**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Inaccurate operator information on wellhead signs.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	04/13/2023
Type	BATTERY		
Comment:	No tank battery sign posted.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	04/13/2023
Type	TANK LABELS/PLACARDS		
Comment:	Inaccurate operator information on labels/placards.		
Corrective Action:	Install labels/placards to comply with Rule 605.h.	Date:	04/13/2023

<b>Emergency Contact Number:</b>			
Comment:	<input type="text" value="(970) 858-8550"/>		Date:
Corrective Action:	<input type="text"/>		<input type="text"/>

<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Unused equipment stored on location.		
Corrective Action:	Remove unused equipment to comply with Rule 606.	Date:	03/28/2023
Type	WEEDS		
Comment:	Weeds have encroached entire production area.		
Corrective Action:	Remove weeds from location to comply with Rule 606.	Date:	03/20/2023

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Pump Jack	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		

Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 2		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Weeds have compromised permeability and capacity of berm.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).			Date: 04/02/2023

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	Open Top		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Weeds have compromised permeability and capacity of berm.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).			Date: 04/02/2023

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		
		Date:

**Flaring:**

Type	
------	--

Comment:		
Corrective Action:		Date:

--	--	--

**Inspected Facilities**

Facility ID: 210984 Type: WELL API Number: 045-06742 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 266868 Type: WELL API Number: 045-09186 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Fail					Degraded waddle BMP
		Compaction				
		Check Dams				
Gravel						
Compaction	Fail					Lack of stabilization
		Ditches				
		Gravel				
		Culverts				
Other	Fail					Insufficient tracking BMPs
Berms						

Comment: 1) Location surface lacks stabilization with insufficient vehicle tracking BMPs in place to minimize transportation of sediment.  
 2) Waddles on west side of pad are degraded and insufficient.

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 03/20/2023

Pits:  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403740677	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6492434">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6492434</a>
708301958	Photo Log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6492433">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6492433</a>