

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/08/2024

Submitted Date:

04/10/2024

Document Number:

708903508

**FIELD INSPECTION FORM**

Loc ID: 323785  
Inspector Name: Smelser, Wayne  
On-Site Inspection:   
2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

ECMC Operator Number: 10550  
Name of Operator: MUSTANG RESOURCES LLC  
Address: PO BOX 13550  
City: BAKERSFIELD State: CA Zip: 93389

**Findings:**

- 14 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Mustang		nwelch@vaqueroenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210803	WELL	PR	10/01/2023	GW	045-06561	YOUBERG 23-24-6S-94W	PR

**General Comment:**

[CECMC Inspection Report Summary](#)  
On 04/08/2024 at approximately 12:42 hours, I, Compliance Specialist, Wayne Smelser Conducted a follow up inspection at MUSTANG RESOURCES LLC YOUBERG 23-24-6S-94W Pad. Location # 323785 in Garfield County Colorado.  
Please refer to inspection 708901775 conducted on 09/22/2023, previous corrective actions have been completed. Location is within High Priority/Density/Black Bear/NSO Habitat areas & Bald Eagle Roost site. Location is approximately 104 yards from Beaver Creek. While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

1. Equipment - Meter not calibrated annually/not in compliance with CECMC rules with a CA date of 05/10/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.  
This is a summary of inspection report.

**Location**

<b>Lease Road:</b>			
	Type Access		
comment:			
Corrective ActionL			Date:

Overall Good:

<b>Signs/Marker:</b>			
	Type BATTERY		
Comment:	No tank battery		
Corrective Action:			Date:
	Type WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
	Comment: 911/888-291-8588		
Corrective Action:			Date: _____

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
	Type LOCATION		
Comment:	Barbed wire		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Gas Meter Run	# 1		
Comment:	Meter not calibrated annually/not in compliance with CECMC rules (please refer to photo log, last meter calibration 2021)		
Corrective Action:	Comply with CECMC gas meter calibration rules		Date: 05/10/2024
Type: Deadman # & Marked	# 1		
Comment:	Marked		
Corrective Action:			Date:
Type: Plunger Lift	# 0		
Comment:	Well not on plunger lift		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible.		
Corrective Action:			Date:

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 210803 Type: WELL API Number: 045-06561 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing, well not on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Compaction						Some light compaction
		Gravel				Sparse to none
Gravel						Sparse to none

Comment: [No other observed BMP's](#)  
[Places with sparse to no gravel & light compaction are present on location. Sparse/no gravel and light compaction could lead to future stabilization and tracking issues.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**ECMC Comments**

Comment	User	Date
<a href="#">Please refer to Equipment for observed compliance issue.</a>	smelserw	04/10/2024
<a href="#">As to the domestic tap &amp; PRV corrective actions from the previous inspection (inspection 708901775) according to operator (Mustang), the domestic tap is not connected to their well &amp; belongs to TEP. CECMC Integrity Engineering Technician Mike Longworth contacted TEP &amp; was informed by Chuck Smith that the Mustang well use to supply gas to nearby a house until it started to not be able to keep up. Then TEP ran a line from their nearby location to the tap in the meter house. Please refer to inspection 701103834 conducted on 09/27/2023 for more info on TEP domestic tap.</a>		

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
708903509	Inspection 708903508 Stormwater photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503819">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503819</a>
708903510	Inspection 708903508 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503820">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6503820</a>