

WELL NAME: LORENCITO 13-2, API #: 071-08516, INSP. # 695109417




PHOTO 1: WELL SIGN



**PHOTO 2: LOCATION**





**PHOTO 3: WELLHEAD AND EQUIPMENT**



**PHOTO 4: APPEARS TO BE A HYDRAULIC LEAK ON THE DRIVE HEAD. Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. CA DATE 4-18-2024.**



**PHOTO 5: AREA OF IMPACTED SOIL NEAR WELLHEAD APPEARS TO BE HYDRAULIC OIL FROM LEAKING DRIVEHEAD (IT APPEARS THAT OPERATOR ATTEMPTED TO COVER IMPACTED SOIL WITH SOIL FROM PIT BERM). Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002, (2).D. CA DATE 4-18-2024.**



**PHOTO 6: OILY WASTE IN ENGINE SKID. COMPLY WITH RULE 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. CA DATE 4-12-2024.**