

WELL NAME: LORENCITO 8-2, API #: 071-09023, INSP. # 695109425



PHOTO 1: WELL SIGN



**PHOTO 2: LOCATION**





**PHOTO 3: WELLHEAD AND EQUIPMENT**



**PHOTO 4: LACK OF BMP'S OR BMP FAILURE HAS RESULTED IN SEDIMENT WASHING DOWN THE ROW BMP DITCH. **INSTALL OR REPAIR BMP'S AND INSPECT AT REGULAR INTERVALS TO PREVENT SEDIMENT MIGRATION PER RULE 1002. CA DATE 5-11-2024.****



**PHOTO 5: ANOTHER IMAGE OF BMP FAILURE NOTED IN PREVIOUS PHOTO.**



**PHOTO 6: OILY WASTE IN OILER SECONDARY CONTAINMENT IS CLOSE TO RUNNING OVER. COMPLY WITH RULE 1002.f.(2)B, Comply with general provisions of the oil and gas act for wildlife protection AND SB-181. IMMEDIATE ACTION IS REQUIRED. CA DATE 4-12-2024.**