

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC SAVAGE 11-35-6-94 W Pad

Location ID: 324139



Photo # 3686 From entrance to location



Photo # 3687 Location



## Inspection Photos

Location Name: MUSTANG RESOURCES LLC SAVAGE 11-35-6-94 W Pad

Location ID: 324139




Photo # 3688 Location



Photo # 3689 Location





## Inspection Photos

Location Name: MUSTANG RESOURCES LLC SAVAGE 11-35-6-94 W Pad

Location ID: 324139



**Photo # 3690 Fencing needs maintenance - post & barbed wire laying on the ground/wildlife hazard**



**Photo # 3691 Fencing needs maintenance - post & barbed wire laying on the ground/wildlife hazard**



## Inspection Photos

Location Name: MUSTANG RESOURCES LLC SAVAGE 11-35-6-94 W Pad

Location ID: 324139



**Photo # 3692 Fencing needs maintenance - post & barbed wire laying on the ground/wildlife hazard**



**Photo # 3693 Fencing needs maintenance - post & barbed wire laying on the ground/wildlife hazard**



## Inspection Photos

Location Name: MUSTANG RESOURCES LLC SAVAGE 11-35-6-94 W Pad

Location ID: 324139



Photo # 3694 Gas meter calibration record for SAVAGE 11-35-6-94 W well not conspicuously displayed at meter



Photo # 3695 Gas meter calibration record for SAVAGE 11-35-6-94 W well not conspicuously displayed at meter

## Inspection Photos

Location Name: MUSTANG RESOURCES LLC SAVAGE 11-35-6-94 W Pad

Location ID: 324139



Photo # 3696 Debris



Photo # 3697 Debris