

# Inspection Photos

API: 061-05028

Operator: RENEGADE OIL & GAS COMPANY LLC

Inspection Date: 4/10/2024

County: Prowers



## Inspection Photos



**Photo 1.** Facing north toward the wellsite. The area around the well has not revegetated. There is bare soils extending approximately 100 ft. out from the well that needs to be reclaimed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API: 061-05028 | Date: 4/10/2024

## Inspection Photos



**Photo 2.** Facing toward the TA''d well.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API: 061-05028 | Date: 4/10/2024

## Inspection Photos



**Photo 3.** Facing southwest at the wellsite. There is bare soils extending approximately 100 ft. out from the well that needs to be reclaimed.

