

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/10/2024

Submitted Date:

04/12/2024

Document Number:

713600913

**FIELD INSPECTION FORM**

Loc ID 384474 Inspector Name: COSTA, RYAN On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

ECMC Operator Number: 74165  
Name of Operator: RENEGADE OIL & GAS COMPANY LLC  
Address: 6155 S MAIN STREET #225  
City: AURORA State: CO Zip: 80016

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Ingve, Edward	303-680-4725	ed@renegadeoilandgas.com	
Freese, Steve		steve.freese@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
212916	WELL	TA	02/06/2020	GW	061-06277	STATE 1-16	RI

**General Comment:**

This is a reclamation inspection at the STATE #1-16 location.  
See attached photos and additional details within this report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective ActionL			Date:
Overall Good: <input checked="" type="checkbox"/>			
Emergency Contact Number:			
Comment:			Date:
Corrective Action:			
<b>Good Housekeeping:</b>			
Type	OTHER		
Comment:	There is an open excavation at the well which needs to be temporarily fenced or protected to prevent livestock or wildlife entry.		
Corrective Action:	Comply with Rule 210.		Date: 04/19/2024
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Venting:</b>			
Yes/No			
Comment:			
Corrective Action:			Date:
<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:			Date:

ECMC Comments		
Comment	User	Date
The form 6S indicates the well was plugged on 11/1/2023. There is an open excavation at the well and the well has been cut and capped below the surface. A form 27 has been submitted for decommissioning of the well and remediation. A follow up reclamation inspection will be performed once remediation has been completed.	CostaR	04/12/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713600914	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6506228">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6506228</a>