

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BORUCH-67S96W/11NESE

Location ID: 334847

Date: 4/10/2024



Location Entrance – Photo #00524



Wellheads – Photo #00525

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BORUCH-67S96W/11NESE

Location ID: 334847

Date: 4/10/2024



Separators – Photo #00528




Tank Battery – Photo #00530

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BORUCH-67S96W/11NESE

Location ID: 334847

Date: 4/10/2024



Illegible Wellhead Sign – Photo #00526

Illegible Wellhead Sign – Photo #00527

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, BORUCH-67S96W/11NESE

Location ID: 334847

Date: 4/10/2024



**Lack of Stabilization/Insufficient Vehicle Tracking BMPs at
Location Entrance/Exit – Photo #00533**