

Inspection Photos

04/12/2023

Operator: VISION ENERGY LLC - 10770

Location ID: 322369

Inspection Doc: 696205748

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
CECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 322369



Photo 1: Photos 1-2 taken from the west end of the Location. Photos provide an overview from north, northeast, southeast to south.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Operator Name: VISION ENERGY LLC - 10770
Location ID: 322369



Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 322369



Photo 3: Photos examples showing cut slopes of the Location. 1004 reclamation requirements including, but not limited to, compaction alleviation, removal of gravel, recontouring/regrading and revegetation activities remain outstanding on the Location and access road. Reclamation work pursuant to Rule 1004.a required to be completed within 12 months after plugging well.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 322369



Photo 4: Photos show the location of the former tank battery facility.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 322369



Photo 5: See comments under photo 4. Gravel requires removal.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 322369



Photo 6: Photo taken from the southwest end of the Location. Photo shows meter-shed equipment remaining on the Location. Equipment requires removal.



COLORADO

Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 322369



Photo 7: Photo example showing anchor equipment remaining. Equipment requires removal.

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 322369



April 12, 2024

Photo 8: Photo shows access road leading to location. Access road requires reclamation.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 322369



Photo 9: Photos taken from the south end of the Location, facing west. Photo examples showing areas of excavation along the flowline, and where separator equipment was located.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 322369



Photo 10: Photos 10-12 examples showing various equipment/trash/debris/rubbish on the Location. Materials/items require removal.

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 322369



Photo 11: See comments under photo 10.



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 322369



Photo 12: See comments under photo 10.

Inspection Photos

Operator Name: VISION ENERGY LLC - 10770

Location ID: 322369



Photo 13: Photos taken from behind the meter shed equipment, on the southwest end of the Location. Photo shows monitoring well on Location.