

Final Reclamation and Stormwater Inspection

Date: 04/10/2024

Operator: SAND HILLS SOCIETY - 76120

Location ID: 403660

Inspection Document #: 708201139

Washington County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Strickler 1-31
Location ID: 403660



Photo 1. Taken north of the pit and well location. It does not appear that any additional reclamation work has been conducted since the previous inspections. The pit remains open and requires additional reclamation work to comply with Rule 1004.

Inspection Photos
Location Name: Strickler 1-31
Location ID: 403660



Photo 2. Taken near the east side of the former pit and well location; see comments in Photo 1.

Inspection Photos
Location Name: Strickler 1-31
Location ID: 403660



Photo 3. Taken near the west side of the former pit and well location; see comments in Photo 1.

Inspection Photos
Location Name: Strickler 1-31
Location ID: 403660



Photo 4. Taken from the northeast corner of the pit. No evidence of reclamation activities observed at the time of this inspection.

Inspection Photos
Location Name: Strickler 1-31
Location ID: 403660



Photo 5. Pipe remains within pit area.

Inspection Photos
Location Name: Strickler 1-31
Location ID: 403660



Photo 6. The former well location (approximated by red arrow) does not appear to have been reclaimed and is not reflective of the adjacent reference area.

Inspection Photos
Location Name: Strickler 1-31
Location ID: 403660



Photo 7. Taken from the southwest corner of the pit. No evidence of reclamation activities observed at the time of this inspection.

Inspection Photos
Location Name: Strickler 1-31
Location ID: 403660



Photo 8. Adjacent reference area photo (cropland) taken south of the pit/well location.