

# Inspection Photos

April 12th, 2024

Operator: MorningStar Operating LLC - 10755

Location ID: 333334

Inspection Document #: 714000665

Archuleta County, CO

Township: NWNE 23 32N 6W N

Corey McDonough - Southwest  
Reclamation Specialist



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Chapin 32-06 23-3, 4  
Location ID: 333334

4/12/24

+37.007077,-107.466491

242° SW



**Photo 1.** View of the well disturbance from the access point facing center.

Inspection Photos  
Location Name: Chapin 32-06 23-3, 4  
Location ID: 333334



**Photo 2.** View of southern fill slope/interim reclamation areas dominated by kochia/russian thistle debris and lacking vegetation. Stormwater BMPs/soil stabilization is needed until long term stabilization is achieved with perennial vegetation.

Inspection Photos  
Location Name: Chapin 32-06 23-3, 4  
Location ID: 333334



**Photo 3.** Unused oil and gas equipment observed at both pump jacks.

Inspection Photos  
Location Name: Chapin 32-06 23-3, 4  
Location ID: 333334

4/12/24  
+37.006663,-107.467030  
193° S



**Photo 4.** Reference area comprised of smooth brome and intermediate wheatgrass.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

API #: 007-06261