

Inspection Photos

April 12th, 2024

Operator: Catamount Energy Partners LLC - 10464

Location ID: 320847

Inspection Document #: 714000667

Archuleta County, CO

Township: NWNE 14 32N 6W N

Corey McDonough - Southwest
Reclamation Specialist



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Cox 2
Location ID: 320847

4/12/24
+37.022365,-107.466179
123° SE



Photo 1. View of the well disturbance from the access point facing center.



API #: 007-06093

Inspection Photos
Location Name: Cox 2
Location ID: 320847



4/12/24
+37.021989,-107.466034
140° SE

Photo 2. View of unused oil and gas fencing stored along the southern edge of the disturbance.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 007-06093

Inspection Photos
Location Name: Cox 2
Location ID: 320847



Photo 3. Patches of cheatgrass (*Bromus tectorum*) observed along the southern edge of the disturbance.

Inspection Photos
Location Name: Cox 2
Location ID: 320847

4/12/24
+37.022076,-107.465429
45° NE



Photo 4. View of unused meter shed stored in the eastern side of the disturbance.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 007-06093

Inspection Photos
Location Name: Cox 2
Location ID: 320847

4/12/24
+37.022129,-107.465316
306° NW



Photo 5. View of the northern interim reclamation area facing north west.
Vegetation comprised of smooth brome and rabbit brush.



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

API #: 007-06093

Inspection Photos
Location Name: Cox 2
Location ID: 320847

4/12/24
+37.022129,-107.465316
356° N



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Photo 6. View of the reference area comprised of sage brush, rabbit brush, smooth brome and squirrel tail.

API #: 007-06093