

# Inspection Photos

04/12/2023

**Operator:** TEP ROCKY MOUNTAIN LLC - 96850

**Location ID:** 418828

**Inspection Doc:** 696205757

Garfield County, CO

Aaron Trujillo  
NW Reclamation Specialist  
CECMC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 418828



**Photo 1:** Photos taken from the east end of the Location, facing southwest and west. Photo provides an overview of the working pad surface and Location.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 418828



**Photo 2:** Photo taken from the east end of the working pad surface, facing west. Photo shows pad lacks stabilization; BMPs to stabilize, as well as to minimize tracking and degradation during wet conditions have not been maintained on Location. Grading along will be insufficient.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 418828



**Photo 3:** Photos taken from the south end of the Location, facing south/southeast. Southern areas of the Location are predominantly bare and unstabilize soils. Erosion degradation evident. BMPs to stabilize slopes, and to minimize erosion, degradation and sediment transport inadequate. Additional reclamation required.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 418828



**Photo 4:** Continued from photo 3. Photo shows sediment deposition due to unstabilized slopes on the southern interim areas.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 418828



April 12, 2024



April 12, 2024

**Photo 5:** Photos taken from the south end of the Location, facing east/southeast. Southern areas of the Location are predominantly bare and unstabilize soils. Erosion degradation evident. BMPs to stabilize slopes, and to minimize erosion, degradation and sediment transport inadequate. Additional reclamation required.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 418828



**Photo 6:** Photos taken from the eastern and southern interim areas of the Location. Reclamation appears to be progressing towards 1003 standards within these areas.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 418828



**Photo 7:** Photos examples showing noxious weeds (Musk thistle) observed on the interim areas of the Location; weeds reached maturity during the 2023 growing season.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 418828



**Photo 8:** Photo shows tank battery signage with missing and inaccurate information.



**COLORADO**

Energy & Carbon Management  
Commission

Department of Natural Resources

## Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 418828



**Photo 9:** Photos show lines at tanks missing required cap/pug.



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources