

Inspection Photos

Loc: 334553

Operator: OXY USA INC

Inspection Date: 4/16/2024

County: HUERFANO



Inspection Photos



Photo 1. Facing southwest toward the Oxy yard. There is trash along the fence line that is also blowing over the fence. Trash needs to be picked ASAP.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 334553 | Date: 4/16/2024

Inspection Photos



Photo 2. There is trash inside the fenced in Oxy yard that which should be picked up.



Inspection Photos



Photo 3. Facing east along the access road. Grading of the road has pushed a row of gravel along the side shown at red arrow which interferes which stormwater drainage off the road to prevent erosion. There is trash at yellow arrow that needs to be pick up.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 334553 | Date: 4/16/2024

Inspection Photos



Photo 4. Facing back west down the access road. Grading of the road has pushed a row of gravel along the side shown at red arrow which is blocking drainage toward the culvert at the yellow arrow.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 334553 | Date: 4/16/2024

Inspection Photos



Photo 5. There are several drainage diversion along the road that need to be seeded and stabilized. Also make sure grading has not blocked these drainage ditches for stormwater diversion..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 334553 | Date: 4/16/2024

Inspection Photos



Photo 6. Facing northeast toward the location.



Inspection Photos



Photo 7. Facing northeast toward the wellsite. Fill material has been brought in to backfill the open excavation..



Inspection Photos



Photo 8. Facing northwest at the location. There is a pile of brush debris that was pushed to this area that must be removed. There are also noxious weeds in this area (Mullein). Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 334553 | Date: 4/16/2024

Inspection Photos



Photo 9. Facing toward the open excavation which the fence has fall apart. This must be fenced immediately to prevent wildlife of livestock from falling in.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 334553 | Date: 4/16/2024

Inspection Photos



Photo 10. The plastic liner is compromised and impacted soil needs to be removed.



Inspection Photos



Photo 11. Facing toward northeast side of the location. There is unused pipe and steel ring that needs to be removed. Disturbed area needs to be reclaimed at right side of the photo.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Loc: 334553 | Date: 4/16/2024