

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/11/2024

Submitted Date:

04/11/2024

Document Number:

708903514

FIELD INSPECTION FORM

Loc ID 322314 Inspector Name: Smelser, Wayne On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 ECMC Operator Number: 10550
 Name of Operator: MUSTANG RESOURCES LLC
 Address: PO BOX 13550
 City: BAKERSFIELD State: CA Zip: 93389

Findings:

- 14 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Mustang		nwelch@vaqueroenergy.com	
Toews, Wesley		wtoews@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210256	WELL	PR	10/01/2023	GW	045-06012	RULISON FEDERAL 35-94-6S-94W	PR

General Comment:

[CECMC Inspection Report Summary](#)
 On 04/11/2024 at approximately 13:21 hours, I, Compliance Specialist, Wayne Smelser
 Conducted an on-site inspection at MUSTANG RESOURCES LLC RULISON FEDERAL 35-94-6S-94W Pad.
 Location # 322314 in Garfield County Colorado.
 Location is within High Priority/Density/Black Bear Habitat areas & in close proximity to NSO Habitat area.
 Location is approximately 272 yards from Porcupine Creek.
 While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- Housekeeping - Unused equipment on location with a CA date of 05/11/2024

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with CECMC rules.
 This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:	No tank battery		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	911/1-888-291-8588		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment on location - extra meter house on location & equipment is not in use		
Corrective Action:	The storage or placement of equipment and supplies not necessary for use on location is prohibited.		Date: 05/11/2024
Type	DEBRIS		
Comment:	Debris - please refer to photo log		
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Equipment:			corrective date
Type: Gas Meter Run	# 2		
Comment:	1 meter house is not hooked up & is not in use/unused equipment, please refer to Housekeeping for CA		
Corrective Action:			Date:
Type: Plunger Lift	# 0		
Comment:	Well is not on plunger lift		
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	No form of pressure monitoring equipment located on bradenhead, bradenhead valve is accessible.		

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 210256 Type: WELL API Number: 045-06012 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing, well is not on plunger lift](#)

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						Light compaction in some areas
		Ditches				
		Gravel				Sparse
		Compaction				
Gravel						Sparse to none in most areas
		Culverts				

Comment: Places with sparse to no gravel & light compaction are present on location. Sparse/no gravel and light compaction could lead to future stabilization and tracking issues.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

ECMC Comments

Comment	User	Date
Please refer to Housekeeping for observed compliance issue.	smelserw	04/11/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403751737	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6505515
708903515	Inspection 708903514 Stormwater photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6505513
708903516	Inspection 708903514 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6505514