

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/10/2024

Submitted Date:

04/11/2024

Document Number:

712100002

**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: FISCHER, ALEX On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Hansen, Logan		logan.hansen@state.co.us	
Binschus, Chris		chris.binschus@state.co.us	
Rowley, Taylor		Taylor_Rowley@oxy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
149021	CENTRALIZED EP WASTE MGMT FAC	AC	07/16/2008		-	DRILLING FLUID MANAGEMENT FACILITY	AC
250445	WELL	SI		GW	123-18248	HSR-MADELINE MAYER 12-34	EI
256727	WELL	SI		GW	123-19917	HSR MAYER 11-34A	EI

**General Comment:**

On April 10, 2024, COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of KERR MCGEE OIL & GAS ONSHORE LP; CE&P ID: 149021 Drill Fluids Management Facility #1. Weather was overcast and the temperature was 55 degrees F. Slight winds from the north. The following is a summary:

CE&P Facility 149021

Sign at the entrance read, "DFMF #1 Closed for Reclamation No Dumping."

The western portion of the Facility (Pod 1A, 1B, 1C, 1D, 2A, 2B, 2C, and 2D appeared to have some crop emerging (1-3" in height).

The eastern portion of the Facility (Pod 3A, 3B, 3C, 3D, 4B, 4C, and 4D appeared to have some vegetation/weeds (1-5' in height).

Trash/debris throughout the northern portions of the Facility, mainly Pod A, 2A, 3A, and 4B. This material consisted of glass jars, small pieces of hoses, and concrete pieces.

Unused equipment stored near trash containers and shed.

Concrete lined ditch along east side of Facility (dry with tumble weeds).

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Good Housekeeping:				
Type	STORAGE OF SUPL			
Comment:	Storage of unused equipment near trash containers and shed.			
Corrective Action:	Comply with Rule 606			Date:
Type	WEEDS			
Comment:	The eastern portion of the Facility (Pod 3A, 3B, 3C, 3D, 4B, 4C, and 4D appeared to have some vegetation/weeds (1-5' in height).			
Corrective Action:	Comply with Rule 606.			Date:
Type	TRASH			
Comment:	Trash/debris throughout the northern portions of the Facility, mainly Pod A, 2A, 3A, and 4B. This material consisted of glass jars, small pieces of hoses, and concrete pieces.			
Corrective Action:	Comply with Rule 606.			Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment: _____				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

### Location Construction

Location ID: 149021 CDP: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

#### Form 2A COAs:

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

#### Wildlife BMPs:

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective  
Action: \_\_\_\_\_

Date: \_\_\_\_\_

#### On Site Inspection (305):

##### Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

##### Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

##### LGD Contact Information:

Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Agreed to Attend: \_\_\_\_\_

##### Summary of Landowner Issues:

\_\_\_\_\_

##### Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

##### Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Inspected Facilities**

Facility ID: 149021    Type: CENTRALIZE    API Number: -    Status: AC    Insp. Status: AC

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 250445    Type: WELL    API Number: 123-18248    Status: SI    Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 256727    Type: WELL    API Number: 123-19917    Status: SI    Insp. Status: EI

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

**ECMC Comments**

Comment	User	Date
<p>On April 10, 2024, COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of KERR MCGEE OIL &amp; GAS ONSHORE LP; CE&amp;P ID: 149021 Drill Fluids Management Facility #1. Weather was overcast and the temperature was 55 degrees F. Slight winds from the north. The following is a summary:  CE&amp;P Facility 149021 Sign at the entrance read, "DFMF #1 Closed for Reclamation No Dumping."  The western portion of the Facility (Pod 1A, 1B, 1C, 1D, 2A, 2B, 2C, and 2D appeared to have some crop emerging (1-3" in height).  The eastern portion of the Facility (Pod 3A, 3B, 3C, 3D, 4B, 4C, and 4D appeared to have some vegetation/weeds (1-5' in height).  Trash/debris throughout the northern portions of the Facility, mainly Pod A, 2A, 3A, and 4B. This material consisted of glass jars, small pieces of hoses, and concrete pieces.  Unused equipment stored near trash containers and shed.  Concrete lined ditch along east side of Facility (dry with tumble weeds).</p>	fischera	04/11/2024

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403750867	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6504609">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6504609</a>
712100003	20240410 Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6504604">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6504604</a>