

# Interim Reclamation and Stormwater Inspection

April 11, 2024

Operator: NGL WATER SOLUTIONS DJ LLC- 10373

Location ID: 443339

Inspection Document #: 697505256

Weld County, CO

SENE Section 28 T1N R67W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: NGL MAJOR FACILITY C2  
Location ID: 443339



**Photo 1.** Google Earth aerial imagery from 5/24/2023 illustrating the location. Operator has failed to install perimeter stormwater BMPs while conducting interim reclamation activities.

Inspection Photos  
Location Name: NGL MAJOR FACILITY C2  
Location ID: 443339



**Photo 2.** Photo taken from the well location, facing East. Photo illustrates the Operator has initiated interim reclamation activities.



**Photo 3.** Photo taken from the well location, facing Northeast. See comments under Photo 2.

Also, if the Operator has already seeded the interim area, the interim area has not been stabilized.

Inspection Photos  
Location Name: NGL MAJOR FACILITY C2  
Location ID: 443339



**Photo 4.** Photo taken from the well location, facing North. See comments under Photo 2.

Note- Operator has not properly tracked the fill slope, which is only aiding stormwater erosion towards an irrigation ditch.



**Photo 5.** Photo taken from the northern interim reclamation area, facing East. Photo illustrates there is no perimeter stormwater BMP, only a remnant insufficient ditch area along small portions of the perimeter. Red arrow illustrates the irrigation ditch.

Also, there is trash observed within the interim reclamation area.

Inspection Photos  
Location Name: NGL MAJOR FACILITY C2  
Location ID: 443339



**Photo 6.** Photo taken from the northern interim reclamation area, facing South. Photo illustrates Operator has not properly tracked the fill slope, which is only aiding stormwater erosion towards an irrigation ditch.

