

Inspection Photos

API: 055-06012

Operator: OXY USA INC

Inspection Date: 4/16/2024

County: HUERFANO



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos



Photo 1. Facing toward the produced water tank. The secondary berm around the tank is insufficient to contain a spill. Red arrow points to small berm which could easily be overtopped by a leak. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:055-06012 | Date: 4/16/2024

Inspection Photos



Photo 2. Facing northwest at the backside of the tank. The secondary containment at the tank is insufficient to contain a spill..



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:055-06012 | Date: 4/16/2024

Inspection Photos



Photo 3. The remediation area where tank was located has been backfilled with sand and gravel.



Inspection Photos



Photo 4. Facing northwest toward the retention pond are where remediation remains ongoing.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:055-06012 | Date: 4/16/2024

Inspection Photos



Photo 5. There is a white material used to backfill the excavated retention pond area and there are concerns this material may not be suitable for reclamation. Operator will need to sample this area for soil suitability.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:055-06012 | Date: 4/16/2024

Inspection Photos



Photo 6. Facing southeast at the down gradient portion of the location. The degraded perimeter wattles were removed however, no new BMP's were installed and there is a creek approximately 10ft' from the edge of the location. Previous corrective action has not been completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:055-06012 | Date: 4/16/2024

Inspection Photos



Photo 7. Facing southwest at the location. .



Inspection Photos



Photo 8. Facing southeast further away from the location. There is a degraded perimeter fence that needs to be maintained. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:055-06012 | Date: 4/16/2024

Inspection Photos



Photo 9. Standing approximately 125' northwest of the location along the flowline area is an eroded out culvert where the creek flows. The culvert needs repaired or removed. Previous corrective action was not completed.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

API:055-06012 | Date: 4/16/2024

Inspection Photos



Photo 10. Facing toward the injection wellhead.



COLORADO
Energy & Carbon Management
Commission

Department of Natural Resources

Inspection Photos



Photo 11. Facing northeast along the fill slope.



Inspection Photos



Photo 12. Observed along the access road were several dilapidated snow fences which need to be removed or repaired. Previous corrective action was not completed.

