

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/18/2024

Submitted Date:

04/18/2024

Document Number:

696306246

FIELD INSPECTION FORM

Loc ID 467102 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 24 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:

ECMC Operator Number: 10651
Name of Operator: VERDAD RESOURCES LLC
Address: 1125 17TH STREET SUITE 550
City: DENVER State: CO Zip: 80202

Contact Information:

Contact Name	Phone	Email	Comment
,		Regulatory@verdadoil.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
467102	LOCATION	AC			-	Bringelson Fed 2021-2029	AC
468747	WELL	PR	02/23/2021	OW	123-50591	Bringelson Fed 2021-05H	PR
468791	WELL	PR	02/23/2021	OW	123-50592	Bringelson Fed 2029-04H	PR
468792	WELL	PR	02/23/2021	OW	123-50593	Bringelson Fed 2029-02H	PR
468793	WELL	PR	02/22/2021	OW	123-50594	Bringelson Fed 2029-03H	PR
468794	WELL	PR	02/23/2021	OW	123-50595	Bringelson Fed 2029-01H	PR
468795	WELL	PR	02/23/2021	OW	123-50596	Bringelson Fed 2021-04H	PR
468796	WELL	PR	02/23/2021	OW	123-50597	Bringelson Fed 2021-02H	PR
468797	WELL	PR	02/23/2021	OW	123-50598	Bringelson Fed 2021-03H	PR
468798	WELL	PR	02/22/2021	OW	123-50599	Bringelson Fed 2021-01H	PR
468799	WELL	PR	02/01/2021	OW	123-50600	Bringelson Fed 2029-05H	PR

General Comment:

[This is a Well PAD and Production Facility Inspection](#)

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unmarked Risers at VRU; see photos		
Corrective Action:	Complete flowline and crude oil transfer line abandonments to comply with Rule 1105.	Date:	05/03/2024
Type	STORAGE OF SUPL		
Comment:	Unused Building Materials in NE Corner of Location; see photos		
Corrective Action:	Comply with Rule 606	Date:	05/20/2024

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: VRT	# 1		
Comment:			
Corrective Action:		Date:	

Type: Bradenhead	# 10		
Comment:	Appear to plumbed to surface		
Corrective Action:			Date:
Type: LACT	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 14		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Instrumental Air Unit		
Corrective Action:			Date:
Type: VRU	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	400 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:				Shares berm with the Crude Oil Tanks		
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	4	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:						Date:
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities									
Facility ID:	467102	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	AC
Producing Well									
Comment:	PR - Active Production Facility								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	468747	Type:	WELL	API Number:	123-50591	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	468791	Type:	WELL	API Number:	123-50592	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	468792	Type:	WELL	API Number:	123-50593	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	468793	Type:	WELL	API Number:	123-50594	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	468794	Type:	WELL	API Number:	123-50595	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	468795	Type:	WELL	API Number:	123-50596	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									
Facility ID:	468796	Type:	WELL	API Number:	123-50597	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10 14 12									

Producing Well			
Comment:	PR		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 468797 Type: WELL API Number: 123-50598 Status: PR Insp. Status: PR

Producing Well			
Comment:	PR		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 468798 Type: WELL API Number: 123-50599 Status: PR Insp. Status: PR

Producing Well			
Comment:	PR		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 468799 Type: WELL API Number: 123-50600 Status: PR Insp. Status: PR

Producing Well			
Comment:	PR		
Corrective Action:		Date:	

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
Routine Field Inspection. Unmarked Risers at VRU. Unused Building Materials in NE Corner of Location	petrie	04/18/2024

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696306247	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6515492