

# Interim Reclamation and Stormwater Inspection

Date: 4/4/24

Operator: Highpoint Operating Corporation - 10071

Location ID: 444840

Inspection Document #: 713900527

Weld County, CO

Logan Hansen  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

# Inspection Photos

Location Name: Anschutz Equus Farms 4-62-28

NWNW

Location ID: 444840



**Photo 1.** The photo was taken at the well location facing Northeast. The photo illustrates secondary contaminants with improper wildlife netting.

**Photo 2.** The photo was taken at the well location facing Southeast. The photo illustrates the topsoil stockpile is dominated by bare soil and Russian thistle.

Inspection Photos

Location Name: Anschutz Equus Farms 4-62-28

NWNW

Location ID: 444840



**Photo 3.** The photo was taken at the well location facing Northeast. The photo illustrates interim areas in the Northeast corner are dominated by Russian thistle.

**Photo 4.** The photo was taken at the well location facing West. The photo illustrates the Northern disturbance boundary fence with tumbleweeds throughout.

Inspection Photos

Location Name: Anschutz Equus Farms 4-62-28

NWNW

Location ID: 444840



**Photo 5.** The photo was taken at the well location facing Northeast. The photo illustrates unmarked risers.

**Photo 6.** The photo was taken at the well location facing Southeast. The photo illustrates the wellhead footprint on the location.

Inspection Photos

Location Name: Anschutz Equus Farms 4-62-28

NWNW

Location ID: 444840



**Photo 7.** The photo was taken at the well location facing East. The photo illustrates tumbleweeds piled around the wellheads.



**Photo 6.** The photo was taken at the well location facing Northwest. The photo illustrates portions of the interim areas appear to be being unmanaged being dominated by tall stands of Russian thistle.

Inspection Photos

Location Name: Anschutz Equus Farms 4-62-28

NWNW

Location ID: 444840



**Photo 9.** The photo was taken at the well location facing Southeast. The photo illustrates tumbleweeds piled around equipment and a hose without a bullplug left outside of secondary containment.

**Photo 10.** The photo was taken at the well location facing North. The photo illustrates soil staining as well as some small excavation around electrical panels.

Inspection Photos

Location Name: Anschutz Equus Farms 4-62-28

NWNW

Location ID: 444840



**Photo 11.** The photo was taken at the well location facing East. The photo illustrates equipment being stored on the production pad.


**Photo 12.** The photo was taken at the well location facing South. The photo illustrates another line without a plug of any kind.

Inspection Photos

Location Name: Anschutz Equus Farms 4-62-28

NWNW

Location ID: 444840



**Photo 12.** The photo was taken at the well location facing Southwest. The photo illustrates a trash receptacle is being left open and allowing trash to distribute around the location.

**Photo 13.** The photo was taken at the well location facing Southwest. Refer to the comment for photo 12.

Inspection Photos

Location Name: Anschutz Equus Farms 4-62-28

NWNW

Location ID: 444840



**Photo 14.** The photo was taken at the well location facing Northeast. The photo illustrates trash blowing out of the receptacle noted in photo 12.