

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/04/2024

Submitted Date:

04/15/2024

Document Number:

713900527**FIELD INSPECTION FORM**

Loc ID 444840	Inspector Name: Hansen, Logan	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 9 Number of Comments 6 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: ECMC Operator Number: <u>10071</u> Name of Operator: <u>HIGHPOINT OPERATING CORPORATION</u> Address: <u>555 17TH ST STE 3700</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		inspections@civiresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444750	WELL	PR	01/01/2022	OW	123-42724	Anschutz Equus Farms 4-62-28-1609B2	RI
444756	WELL	PR	06/04/2018	OW	123-42730	ANSCHUTZ EQUUS FARMS 4-62-28-3225C	RI
444761	WELL	PR	01/09/2018	OW	123-42734	Anschutz Equus Farms 4-62-29-0916C2	RI
444765	WELL	PR	01/09/2018	OW	123-42738	ANSCHUTZ EQUUS FARMS 4-62-29-2417C	RI
444767	WELL	PR	04/01/2023	OW	123-42740	Anschutz Equus Farms 4-62-28-0108C2	RI
444840	LOCATION	AC			-	Anschutz Equus Farms 4-62-28 NWNW	RI
447930	WELL	PR	04/01/2023	OW	123-43682	ANSCHUTZ EQUUS FARMS 4-62-29-0801CNB	RI
447935	WELL	PR	04/01/2023	OW	123-43686	Anschutz Equus Farms 4-62-28-0108C2B	RI
447936	WELL	PR	04/01/2023	OW	123-43687	ANSCHUTZ EQUUS FARMS 4-62-29-0801CS	RI
447941	WELL	AL	07/11/2017	LO	123-43691	Anschutz Equus Farms 4-62-29-0801D2B	AL
447944	WELL	PR	04/01/2023	OW	123-43694	Anschutz Equus Farms 4-62-28-0108B2B	RI

General Comment:

This is an Interim Reclamation and Stormwater Inspection.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**

Type			
Comment:	Stained soil observed on the location and unplugged hoses throughout the production pad.		
Corrective Action:	Remove stained soil per Rule 912.a.		Date: 05/15/2024
Type	TRASH		
Comment:	Trash receptacle is being left open and allowing trash to blow and distribute across the production facility.		
Corrective Action:	Comply with Rule 606.		Date: 04/22/2024
Type			
Comment:	Wildlife netting was incorrectly installed, and should cover the entire secondary containment.		
Corrective Action:	Install wildlife protection equipment correctly per Rule 608.		Date: 04/22/2024
Type	STORAGE OF SUPL		
Comment:	A pallet of wattle was observed being stored on the production pad.		
Corrective Action:	Comply with Rule 606.		Date: 04/30/2024
Type	WEEDS		
Comment:	Weed debris in the form of tumbleweeds were observed around wellheads, production equipment and throughout the interim areas. Tumbleweeds are a troublesome annual non-native weed that easily breaks off at the stem. Operator failed to control and manage weeds to prevent weed waste and prevent the spread of seeds onto adjacent lands.		
Corrective Action:	Comply with Rule 606 to remove weed debris.		Date: 04/22/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 444750	Type: WELL	API Number: 123-42724	Status: PR	Insp. Status: RI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444756	Type: WELL	API Number: 123-42730	Status: PR	Insp. Status: RI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444761	Type: WELL	API Number: 123-42734	Status: PR	Insp. Status: RI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444765	Type: WELL	API Number: 123-42738	Status: PR	Insp. Status: RI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444767	Type: WELL	API Number: 123-42740	Status: PR	Insp. Status: RI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 444840	Type: LOCATION	API Number: -	Status: AC	Insp. Status: RI
---------------------	----------------	---------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 447930	Type: WELL	API Number: 123-43682	Status: PR	Insp. Status: RI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 447935	Type: WELL	API Number: 123-43686	Status: PR	Insp. Status: RI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 447936	Type: WELL	API Number: 123-43687	Status: PR	Insp. Status: RI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 447941	Type: WELL	API Number: 123-43691	Status: AL	Insp. Status: AL
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Facility ID: 447944	Type: WELL	API Number: 123-43694	Status: PR	Insp. Status: RI
---------------------	------------	-----------------------	------------	------------------

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? _____

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? _____

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? PassProduction areas stabilized ? Pass

1003c. Compacted areas have been cross ripped? _____

1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____

Cuttings management: _____

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____

Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATIONCropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment Appears interim reclamation activities have been performed to reduce disturbance areas only needed for production operations. Vegetation throughout the interim areas has not met Rule 1003 standards and will remain IN-PROCESS. Operator shall continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management. Operator shall submit a Form 4 Interim Reclamation Complete notice when the location meets Rule 1003 standards. ECMC may conduct inspections prior to receiving said notice to ensure compliance with Rule 1003.

Corrective Action _____ Date _____

Overall Interim Reclamation In Process**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND

Reminder: _____

Comment: _____

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads _____ Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% _____

TRANSECT RESULTS OF REFERENCE AREA% _____

TOTAL % OF DESIRABLE VEGETATION COVER _____

VEGETATIVE COVER _____

Inspector Name: Hansen, Logan

Comment:						Date _____
Corrective Action:						
Overall Final Reclamation		Well Release on Active Location <input type="checkbox"/>		Multi-Well Location <input type="checkbox"/>		
<u>Storm Water:</u>						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<div style="display: flex; justify-content: space-between;"><div style="width: 15%;">Comment:</div><div style="width: 70%; border: 1px solid black; padding: 5px;"><p style="color: blue;">At the time of this inspection, no erosion issues were observed at the location or along the access road.</p><p style="color: blue;">Operator shall continue to monitor and manage this site for stormwater run on and runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.</p></div><div style="width: 15%;">Date: _____</div></div> <div style="display: flex; justify-content: space-between; margin-top: 10px;"><div style="width: 15%;">Corrective Action:</div><div style="width: 70%; border: 1px solid black; height: 20px;"></div><div style="width: 15%;">Date: _____</div></div>						
Pits: <input type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713900528	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=6515812