

# Interim Reclamation and Stormwater Inspection

Date: 04/17/2024

Operator: HIGHPOINT OPERATING CORPORATION -  
10071

Location ID: 439471

Inspection Document #: 708201153

Weld County, CO

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Coffelt 5-61-35  
Location ID: 439471



**Photo 1.** Tumbleweed accumulations around equipment need to be removed.

Inspection Photos  
Location Name: Coffelt 5-61-35  
Location ID: 439471



**Photo 2.** Tumbleweed accumulations around equipment need to be removed.

Inspection Photos  
Location Name: Coffelt 5-61-35  
Location ID: 439471



**Photo 3.** Tumbleweed accumulations around equipment need to be removed.

Inspection Photos  
Location Name: Coffelt 5-61-35  
Location ID: 439471



**Photo 4.** Tumbleweed accumulations around equipment need to be removed.

Inspection Photos  
Location Name: Coffelt 5-61-35  
Location ID: 439471



**Photo 5.** Tumbleweed accumulations and debris/trash need to be removed.

Inspection Photos  
Location Name: Coffelt 5-61-35  
Location ID: 439471



**Photo 6.** Stained soil within secondary containment needs to be properly cleaned up and removed.



**Photo 7.** Stained soil within secondary containment needs to be properly cleaned up and removed.

Inspection Photos  
Location Name: Coffelt 5-61-35  
Location ID: 439471



**Photo 8.** Stained soil around buried vessel needs to be cleaned up and properly disposed of.



**Photo 9.** Stained soil around equipment needs to be properly cleaned up and disposed of.

Inspection Photos  
Location Name: Coffelt 5-61-35  
Location ID: 439471



**Photo 10.** Debris/trash within secondary containment needs to be removed.

Inspection Photos  
Location Name: Coffelt 5-61-35  
Location ID: 439471



**Photo 11.** Stained soil outside of secondary equipment needs to be removed and properly disposed of.

Inspection Photos  
Location Name: Coffelt 5-61-35  
Location ID: 439471



**Photo 12.** Container outside of secondary containment needs to be removed or placed inside of secondary containment.



**Photo 13.** Southern interim areas consist primarily of russian thistle.



**Photo 14.** Northern interim areas have some desirable vegetation however, some areas do not have uniform vegetation cover and there is evidence of kochia and russian thistle in the early growth stages that will need to be properly managed for.

Inspection Photos  
Location Name: Coffelt 5-61-35  
Location ID: 439471



**Photo 15.** Northern interim areas, facing southwest; see comments in Photo 14.

Inspection Photos  
Location Name: Coffelt 5-61-35  
Location ID: 439471



**Photo 16.** Northern interim areas, facing southwest; see comments in Photo 14.

Inspection Photos  
Location Name: Coffelt 5-61-35  
Location ID: 439471



**Photo 17.** Fence posts from the initial location construction do not appear to be in use and need to be removed. Located on the northeast corner of the location.