

# Interim Reclamation and Stormwater Inspection

Date: 04/17/2024

Operator: BONANZA CREEK ENERGY OPERATING  
COMPANY LLC - 8960

Location ID: 441005

Inspection Document #: 708201158

Weld County, CO

Dylan Edwardson  
Reclamation Specialist, ECMC



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources

Inspection Photos  
Location Name: Pronghorn D-28 Pad  
Location ID: 441005



**Photo 1.** Tumbleweed accumulations within equipment.

Inspection Photos  
Location Name: Pronghorn D-28 Pad  
Location ID: 441005



**Photo 2.** Southern interim areas consist mainly of undesirable vegetations and bare/exposed soils.

Inspection Photos  
Location Name: Pronghorn D-28 Pad  
Location ID: 441005



**Photo 3.** Degraded straw wattle at the SE corner of the location (sediment trap) is now considered debris.

Inspection Photos  
Location Name: Pronghorn D-28 Pad  
Location ID: 441005



**Photo 4.** Center interim areas are not progressing towards Rule 1003 standards with areas of non-uniform vegetation cover.

Inspection Photos  
Location Name: Pronghorn D-28 Pad  
Location ID: 441005



**Photo 5.** Eastern interim areas are primarily undesirable vegetation (russian thistle and kochia).

Inspection Photos  
Location Name: Pronghorn D-28 Pad  
Location ID: 441005



**Photo 6.** Northern interim areas appear to have been recently drill seeded. Some desirable germination was observed.

Inspection Photos  
Location Name: Pronghorn D-28 Pad  
Location ID: 441005



**Photo 7.** Northern interim area with drill cuttings incorporation; it appears this area has been recently drill seeded, however, no germination was observed. Soils are bare and unstabilized.

Inspection Photos  
Location Name: Pronghorn D-28 Pad  
Location ID: 441005



**Photo 8.** Tumbleweed accumulations within equipment (wellheads).