

Final Reclamation and Stormwater Inspection

Date: 04/17/2024

Operator: BONANZA CREEK OPERATING COMPANY
LLC - 8960

Location ID: 305298

Inspection Document #: 708201162

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: Pronghorn 41-16
Location ID: 305298



Photo 1. Access road does not appear to be properly stabilized as the road is primarily bare/exposed soil.

Inspection Photos
Location Name: Pronghorn 41-16
Location ID: 305298



Photo 2. The former wellhead/pumpjack area does not appear to be properly stabilized as it is primarily bare/exposed soil.

Inspection Photos
Location Name: Pronghorn 41-16
Location ID: 305298



Photo 3. The former tank battery area does not appear to be properly stabilized as it is primarily bare/exposed soil.

Inspection Photos
Location Name: Pronghorn 41-16
Location ID: 305298



Photo 4. Reference area photo taken northwest of the former location. Desirable species observed is primarily blue grama.