

Interim Reclamation and Stormwater Inspection

Date: 04/17/2024

Operator: BONANZA CREEK OPERATING COMPANY
LLC - 8960

Location ID: 428090

Inspection Document #: 708201166

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Inspection Photos
Location Name: State Pronghorn P-16 Pad
Location ID: 428090



Photo 1. Southern interim areas are primarily undesirable vegetation (e.g. russian thistle).

Inspection Photos
Location Name: State Pronghorn P-16 Pad
Location ID: 428090



Photo 2. Southern interim areas are primarily undesirable vegetation (e.g. russian thistle).

Inspection Photos
Location Name: State Pronghorn P-16 Pad
Location ID: 428090



Photo 3. Production areas are not properly stabilized as they are primarily exposed soils.

Inspection Photos
Location Name: State Pronghorn P-16 Pad
Location ID: 428090



Photo 4. Stained soils on the east side of the tank battery.

Inspection Photos
Location Name: State Pronghorn P-16 Pad
Location ID: 428090



Photo 5. Debris near tank battery.

Inspection Photos
Location Name: State Pronghorn P-16 Pad
Location ID: 428090



Photo 6. Tank labels are peeling/faded/cracked.

Inspection Photos
Location Name: State Pronghorn P-16 Pad
Location ID: 428090



Photo 7. Open excavation in relation to remediation project #33589. Operator shall continue to follow 900 series rules for project closure and maintain fencing around all open excavations.

Inspection Photos
Location Name: State Pronghorn P-16 Pad
Location ID: 428090



Photo 8. Debris observed on the east side of the location.

Inspection Photos
Location Name: State Pronghorn P-16 Pad
Location ID: 428090



Photo 9. Debris, including tumbleweed accumulations around equipment, on east side of the location.

Inspection Photos
Location Name: State Pronghorn P-16 Pad
Location ID: 428090



Photo 10. Debris/trash within tank battery secondary containment.

Inspection Photos
Location Name: State Pronghorn P-16 Pad
Location ID: 428090



Photo 11. Stained soil at tank battery.

Inspection Photos
Location Name: State Pronghorn P-16 Pad
Location ID: 428090



4/17/24, 12:26 PM
327° NW
ECMC

Photo 12. Debris near pumpjack.

Inspection Photos
Location Name: State Pronghorn P-16 Pad
Location ID: 428090



Photo 13. Stained soil at pumpjack well API 123- 35220 (left) and well API 123-36470 (right).

Inspection Photos
Location Name: State Pronghorn P-16 Pad
Location ID: 428090



Photo 14. Debris/trash observed on the west side of the location.

Inspection Photos
Location Name: State Pronghorn P-16 Pad
Location ID: 428090



Photo 15. Debris/trash observed on the west side of the location.

Inspection Photos
Location Name: State Pronghorn P-16 Pad
Location ID: 428090



Photo 16. Northern interim areas are primarily undesirable vegetation (e.g. russian thistle) and weed debris.

Inspection Photos
Location Name: State Pronghorn P-16 Pad
Location ID: 428090



Photo 17. Western interim areas are primarily exposed soils.