

Inspection Photos

Location Name: Story Gulch Unit H34 496 Pad

Location ID: #335941

Inspection Date: April 18, 2024



Photo #1 – Sign at entrance to pad.



Photo #2 – Unused sign/debris located at NW corner of pad.



Inspection Photos

Location Name: Story Gulch Unit H34 496 Pad

Location ID: #335941

Inspection Date: April 18, 2024



Photo #3 – Rutted area north of separators.



Photo #4 – Rutted area at pad entrance and north of tank battery.



Inspection Photos

Location Name: Story Gulch Unit H34 496 Pad

Location ID: #335941

Inspection Date: April 18, 2024



Photo #5 – Trash and debris in separator area.



Photo #6 – View of freshwater pit from northwest.

Inspection Photos

Location Name: Story Gulch Unit H34 496 Pad

Location ID: #335941

Inspection Date: April 18, 2024



Photo #7 – Damaged valve can at NW corner of pit.



Photo #8 - Damaged valve can at NW corner of pit (2).



Inspection Photos
Location Name: Story Gulch Unit H34 496 Pad
Location ID: #335941
Inspection Date: April 18, 2024



Photo #9 - Damaged valve can at NW corner of pit (3).



Photo #10 – Hose storage on west side of pit.

Note: hoses in high traffic area appeared to have been damaged by vehicle traffic.

Inspection Photos

Location Name: Story Gulch Unit H34 496 Pad

Location ID: #335941

Inspection Date: April 18, 2024



Photo #11 – Unidentified, gray material on pad surface toward south end of pad.



Photo #12 – Larger accumulation of unidentified, gray material on pad surface toward southwest end of pad.



Inspection Photos

Location Name: Story Gulch Unit H34 496 Pad

Location ID: #335941

Inspection Date: April 18, 2024



Photo #13 – Materials storage south of pit (Richlawn turf food).



Photo #14 – Damaged containers of soil amendments.

Inspection Photos

Location Name: Story Gulch Unit H34 496 Pad

Location ID: #335941

Inspection Date: April 18, 2024



Photo #15 – Damaged container of Profile ProMatrix Engineered Bonded Fiber Matrix in storage area.



Photo #16 - Former container of Profile ProMatrix Engineered Bonded Fiber Matrix in storage area.

Note: this material still contained portions of the wrapping (circled in red).

Inspection Photos

Location Name: Story Gulch Unit H34 496 Pad

Location ID: #335941

Inspection Date: April 18, 2024



Photo #17 – Rutted area north of tank battery (view from SW).



Photo #18 – Unmarked rig anchor located northeast of wellheads.

Inspection Photos

Location Name: Story Gulch Unit H34 496 Pad

Location ID: #335941

Inspection Date: April 18, 2024



Photo #19 - Unmarked rig anchor located southeast of wellheads.



Photo #20 – Uncapped wellhead equipment in well cellar.

Note: Well cellar contained unidentified fluid on inspection date. No hydrocarbon odors or sheen were observed in this area during inspection.

Inspection Photos

Location Name: Story Gulch Unit H34 496 Pad

Location ID: #335941

Inspection Date: April 18, 2024



Photo #21 - Uncapped wellhead equipment in well cellar.



Photo #22 – Trash observed at entrance to pad, looking NW.

Note: Well cellar contained unidentified fluid on inspection date. No hydrocarbon odors or sheen were observed in this area during inspection.

Inspection Photos

Location Name: Story Gulch Unit H34 496 Pad

Location ID: #335941

Inspection Date: April 18, 2024



Photo #23 – Trash inside of retention pond located at NE corner of pad.