

# Inspection Photos

API: 055-06316

Operator: OXY USA INC

Inspection Date: 4/16/2024

County: HUERFANO



**COLORADO**

**Energy & Carbon Management  
Commission**

Department of Natural Resources

## Inspection Photos



**Photo 1.** Facing south along the access road. There is erosion along the roadside that has not been repaired and BMP's have not been installed. Previous corrective action has not been completed.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:055-06316 | Date: 4/16/2024



## Inspection Photos



**Photo 2.** There is sediment that has been transported offsite along the road.



**COLORADO**  
Energy & Carbon Management  
Commission  
Department of Natural Resources



## Inspection Photos



**Photo 3.** Facing back north the steep grade of access road. Stormwater is not being diverted off the road which is causing erosion of the road. Stormwater should be divert toward red arrow and into a sediment trap.



**COLORADO**  
Energy & Carbon Management  
Commission

Department of Natural Resources

API:055-06316 | Date: 4/16/2024



## Inspection Photos



**Photo 4.** Facing southwest toward the wellsite.

