

Construction and Stormwater Inspection

Date: 04/19/2024

Operator: PDC ENERGY INC - 69175

Location ID: 485098

Inspection Document #: 708201177

Weld County, CO

Dylan Edwardson
Reclamation Specialist, ECMC



COLORADO

**Energy & Carbon Management
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Denali State 5N67W13 1-23
Location ID: 485098



Photo 1. Taken near the start of the access road, facing west. It appears that topsoil has been salvaged and a stormwater ditch has been constructed.

Inspection Photos
Location Name: Denali State 5N67W13 1-23
Location ID: 485098



Photo 2. Taken near the east side of the disturbance area. Photo illustrates topsoil salvage activities and cut/fill operations.

Inspection Photos
Location Name: Denali State 5N67W13 1-23
Location ID: 485098



Photo 3. Taken near the east side of the disturbance area. Photo illustrates topsoil salvage activities and cut/fill operations.

Inspection Photos
Location Name: Denali State 5N67W13 1-23
Location ID: 485098



Photo 4. Stormwater ditch constructed along the east side of the disturbance area.

Inspection Photos
Location Name: Denali State 5N67W13 1-23
Location ID: 485098



Photo 5. Stormwater ditch constructed along the north side of the disturbance area. Topsoil stockpile illustrated by red arrow.

Inspection Photos
Location Name: Denali State 5N67W13 1-23
Location ID: 485098



Photo 6. Stormwater ditch constructed along the north side of the disturbance area. Topsoil stockpile illustrated by red arrow.

Inspection Photos
Location Name: Denali State 5N67W13 1-23
Location ID: 485098



Photo 7. Taken near the northwest corner of the disturbance area. Topsoil salvage activities were ongoing at the time of this inspection.

Inspection Photos
Location Name: Denali State 5N67W13 1-23
Location ID: 485098



Photo 8. Stormwater ditch constructed along the west side of the disturbance area. Topsoil stockpile illustrated by red arrow.

Inspection Photos
Location Name: Denali State 5N67W13 1-23
Location ID: 485098



Photo 9. Taken near the west side of the disturbance area. Photo illustrates topsoil salvage activities and cut/fill operations are ongoing.

Inspection Photos
Location Name: Denali State 5N67W13 1-23
Location ID: 485098



Photo 10. Topsoil stockpile located in the southwest corner of the disturbance area where the future production facility will be located. Operator shall ensure that all topsoil is stabilized in compliance with Rule 1002.c.

Inspection Photos
Location Name: Denali State 5N67W13 1-23
Location ID: 485098



Photo 11. Taken near the southwest corner of the disturbance area. See comments in Photo 10.

Inspection Photos
Location Name: Denali State 5N67W13 1-23
Location ID: 485098



Photo 12. Looking northeast along the access road start from the disturbance area. It appears that topsoil has been salvaged and a stormwater ditch has been constructed.

Inspection Photos
Location Name: Denali State 5N67W13 1-23
Location ID: 485098



Photo 13. Taken near the center portion of the access road, facing east. See comments in Photo 12.

Inspection Photos
Location Name: Denali State 5N67W13 1-23
Location ID: 485098



Photo 14. Taken near the center portion of the access road, facing east. See comments in Photo 12. It appears that stormwater BMPs are planned for the low point of the access road.

Inspection Photos
Location Name: Denali State 5N67W13 1-23
Location ID: 485098



Photo 15. Taken near the eastern portion of the access road, facing east. See comments in Photo 12.

Inspection Photos
Location Name: Denali State 5N67W13 1-23
Location ID: 485098



Photo 16. Taken near the eastern portion (start) of the access road, facing east. See comments in Photo 12.